

Date: May 12th 2017

Wowrack interconnect revision

This document serves as a revision to the Wowrack existing interconnect with the SIX, dated April 11th 2017, pending approval by the SIX Board. We are providing the information based on the SIX policies and rules at <https://www.seattleix.net/rules>.

Wowrack need to add its existing SIX extension switches on the 1st floor with Dell Force10 S4810 switch as it provides more capacity and flexibility with its SFP/SFP+ ports. We also replacing the SIX extension switch on the 3rd floor from a Force10 S25 to Force10 S4810, in the end this process will add more capacity and flexibility for SIX participants who wish to connect with copper or fiber cross-connect through Wowrack SIX Extension.

SIX policy and rules will be enforced on this new switch. Ports will err-disable for the following reasons:

- Exceeding a maximum MAC count of one MAC address per VLAN
- BPDUs

All administrative and management control of the switch is managed by Wowrack NOC at noc@wowrack.com - 206-522-4402.

Attached on this document is the revised interconnect network diagram.

